




RIVER MILE 10.9 REMOVAL ACTION WATER QUALITY MONITORING PROGRAM WEEKLY REPORT

Summary of water quality monitoring for the week ending August 18, 2013

Dredging operations, which began on August 3, 2013, are being continuously monitored to ensure that water quality is maintained at acceptable levels. To monitor water quality, a number of sampling locations have been established as shown on the map below.

Operations were conducted within acceptable water quality limits.

Turbidity Buoy #4 had to be serviced due to debris buildup and detector interference. As a result, data are not reported for Sunday (note that no dredging was performed Sunday).




Water Quality Monitoring Data


Weekly Turbidity (NTU)

	Average	Stan. Dev.
Buoy #1	12	6
Buoy #2	19	16
Buoy #3	8.7	4.6
Buoy #4	21	16

Turbidity - Week Ending August 18, 2013

(Times in which there was dredging activity are shown in yellow)





Water Quality Monitoring Locations